

HOW TO USE THE SCALE

Press ON/OFF button to switch on the scale and wait until "0.0" is shown on the display screen, Place the objects on the center of the platform, When the display is stable check the readout, press MODE button to switch between the weighing units. Press ON/OFF again to turn off the scale after use.

HOW TO USE TARE FUNCTION

Turn on the scale, Place the empty container of weighing objects on the center of the platform, press TARE button and the screen shows "0.0", Take the container off and place the items in the container then place the container again on the center of the platform, The readout is the net weight of the items in the container.

HOW TO CALIBRATE THE SCALE

Turn on the scale and after the scale shows "0.0" then press and hold the "Mode" for 3 seconds, the scale will display "CAL" then release the "Mode" and press it again, the "Cal" will flash 3 times and followed with the required weight, Place the weight on the scale and the scale will show "PASS", the calibration is completed, if it is still not accurate enough, please calibrate it again.